

MDCPS Facility Inspection Report Fienberg/Fisher K-8 Ctr.

District Inspection performed on 6/3/2024

Building Number	Room Number	Deficiency Type	Description/Action Taken	Deficiency Number
1	011	M	Secure "EXIT" sign hardware on column adjacent cash register - serving line - Dining Room.	SI076124001
1	011A	C	Mechanical room vented into dining room area adjacent serving line	SI076118003
1	012	M	Spray nozzle not directly over (2) burner stove - Food Prep	SI076122003
1	012	M	Secure "EXIT" sign hanging by exposed wires above receiving door - Food Prep Area.	SI076124002
1	012	M	First door left to right has missing door hold hardware - Serving Line.	SI076124003
2	003	M	Elevator cert has expired 7/22 - SS #70731	SI076124004
2	005	M	Emergency light inoperable - Computer Lab.	SI076122005
2	005A	M	Provide cover panel for Main 5 of 6 with exposed wires, relays, switches - Electrical Room.	SI076122007
2	8087	C	Provide illuminated "exit" signage hardware with directional chevron 1st floor east and west covered walk building # 2.	SI076116003
2	8087	C	Provide "EXIT" sign hardware with directed chevron East 2nd Floor - Covered Walk adjacent 010 - CR	SI076124005
3	015	M	FACP indicate trouble - Office - Bldg #3.	SI076124006
3	015G	M	Emergency light inoperable-Women's RR	SI076121004

Deficiency Type

S- School Site Responsibility M- Maintenance Responsibility C- Long Term Capital Correction
 Imminently dangerous conditions will be addressed immediately.

Division of Safety and Emergency Management 305-995-4900

MDCPS Facility Inspection Report Fienberg/Fisher K-8 Ctr.

District Inspection performed on 6/3/2024

Building Number	Room Number	Deficiency Type	Description/Action Taken	Deficiency Number
4	AUD	M	Certificate of Compliance missing from wheelchair lift - Aud.	SI076122011
6	STAGE	M	Handrail missing from stage stairs (2) Aud	SI076121005
7	0000	M	Post "rescue window " signage classrooms 023, 024, 025, 026.	SI076121010
7	023	S	Post evacuation diagram - classrooms 023, 024, 025, 026.	SI076124007
7	8087	M	Provide (1) handrail to egress exit steps SW covered walk adjacent 020	SI076113020
8	0000	C	Install 42" inch guard rail for building 8, 9, and 10 exterior corridor.	SI076102008
8	0000	M	Post "rescue window " signage-class-rooms 331, 312, 314, 315.	SI076121015
8	110	M	FACP indicate trouble - MB Adult Office	SI076124009
8	112B	M	Smoke Detector missing from location of FACP - Main Office	SI076122013
8	112B	M	FACP inoperable - No Power - Main Office.	SI076124008
8	200	S	Extinguisher access obstructed by fish tank - Lab - CR	SI076124010
8	200	S	Post evacuation diagram - Lab	SI076124012
8	201	S	Post evacuation diagram - Computer Lab.	SI076124011

Deficiency Type

S- School Site Responsibility M- Maintenance Responsibility C- Long Term Capital Correction

Imminently dangerous conditions will be addressed immediately.

Division of Safety and Emergency Management 305-995-4900

MDCPS Facility Inspection Report Fienberg/Fisher K-8 Ctr.

District Inspection performed on 6/3/2024

Building Number	Room Number	Deficiency Type	Description/Action Taken	Deficiency Number
10	118	M	Post "Fire Alarm Pull Station Inside" signage-CR	SI076121018
10	118A	C	There shall be no enclosed usable space under stairs	SI076109030
10	313	M	smoke detector missing from location 3rd floor chase adjacent water cooler.	SI076112059
11	123	C	Post pull station inside signage classroom 123	SI076120012
11	128	M	Provide GFCI to existing duplex outlet custodial mop sink closet	SI076115029
11	132	C	Areas below exit stairs shall not be used as a closet for storage of any king or any other purpose.	SI076111086
11	8087	C	Provide (1) handrail to NE egress exit steps building #11 covered walk also NW building #10.	SI076113042
12	124	M	Post "Pull Station Inside" signage exterior of exit door - Art Room	SI076122017
12	125	M	Post "Fire Alarm Pull Station Inside" signage (Miami Beach Adult Ed Center)	SI076121019
12	224	M	Replace several missing ceiling tile above A/C Unit-CR-(MBA Ed)	SI076121021
12	224	M	Emergency light inoperable- foyer to exit stairs (MBA)	SI076121022
12	MBA 126	M	Rescue windows has been replaced with an Air condition wall unit PC #115 25 42 MBA	SI076122016

Deficiency Type

S- School Site Responsibility M- Maintenance Responsibility C- Long Term Capital Correction
 Imminently dangerous conditions will be addressed immediately.

Division of Safety and Emergency Management 305-995-4900

MDCPS Facility Inspection Report Fienberg/Fisher K-8 Ctr.

District Inspection performed on 6/3/2024

Building Number	Room Number	Deficiency Type	Description/Action Taken	Deficiency Number
12	MBA000	C	Unable to identify emergency lights throughout 1st floor building # 12-125, 126, 127b classrooms. mba	SI076117016
14	142	M	Repair ceiling leak - See Teacher - Music	SI076122019
14	142	M	Repair damaged exit ramp handrail - Music Room	SI076124016
14	143	M	Post "Pull Station Inside" signage on exterior of exit door - CR	SI076122020
14	143	M	Repair ceiling leak - CR - Music Room	SI076123005
16	9101	M	Fire extinguisher (2) are located inside fire hose cabinets post "fire extinguisher inside " signage above both locations - gum.	SI076116027
16	9106	M	Emergency light inoperable - teacher's Planning room - GYM	SI076122025
16	9107	M	Repair ceiling leak above mechanical room - GYM	SI076124017
16	GYM	M	Post load occupancy signage (GYM) (565)	SI076103078
16	GYM	M	Emergency light inoperable BRR-GRR-GYM	SI076121023
89	001	S	Extinguisher access obstructed by Storage Panda Center - Relocatable	SI076124013
89	001	S	S.E. exit door access obstructed by Storage Panda Center - Relocatable	SI076124014
89	001	M	S.E. emergency light inoperable - Panda Center - Relocatable.	SI076124015

Deficiency Type

S- School Site Responsibility M- Maintenance Responsibility C- Long Term Capital Correction

Imminently dangerous conditions will be addressed immediately.

Division of Safety and Emergency Management 305-995-4900

MDCPS Facility Inspection Report Fienberg/Fisher K-8 Ctr.

District Inspection performed on 6/3/2024

Building Number	Room Number	Deficiency Type	Description/Action Taken	Deficiency Number
-----------------	-------------	-----------------	--------------------------	-------------------

Deficiency Type

S- School Site Responsibility M- Maintenance Responsibility C- Long Term Capital Correction

Imminently dangerous conditions will be addressed immediately.

Division of Safety and Emergency Management 305-995-4900